


CALIWELD


GCU 1.0

TM Texas measuring voltage


120 V max



CP TIG connections



CP TIG connections



EM


Tachometer 30m/min max

Gas 30l/min argon max

Voltage 120V max

Current 500A max


Remote control




RC Remote control




CT Cable Texas. 50 mm²




TG Gas connection




USB Cable USB




TV Tachometer 30/min max



PM Clamp measurement



CP



TM




TV




TG


CABLE CALIBRATION MODE




TIG



MMA



MIG



CABLE WELDING MODE